

5 comprising the steps consisting in:

10 layer and the decoration layer;

with the article;

15 decoration layer onto the article, the varnish layer
being such as to be transferred locally onto the article
together with the decoration layer;

- withdrawing the backing layer; and

· causing the layer of varnish that has been
20 transferred onto the article to harden by exposing it to
said radiation.